

NEW PRODUCT RELEASE

Protex Commercial Disc Rotors



CDR1043

Replaces: MERITOR (ROR) 21227349
378mm Dia. x 250mm PCD x 10xM16 Holes
With ABS Pole Ring
Brake System: Meritor Elsa/DX195



CDR1050

Replaces: IVECO 2995702, 2995894, 7187541
377mm Dia. x 144mm PCD x 14xM15.3 Holes
IVECO EuroCargo 130-160 Series



CDR1049

Replaces: DAF K004322, 1387439, 1640561
432mm Dia. x 258mm PCD
DAF Series: XF95, CF65, CF75, CF85
FODEN: Alpha Series

Protex Commercial Disc Pads



CDP1041

247.6x109.7x30mm

Replaces: BPW 09.801.06.96.0
Brake System: Knorr SB4345T (SB7)



CDP1042

210.5x109.5x30mm

Replaces: SAF 3.057.0084.00
Brake System: WABCO PAN22-1

Protex Commercial Disc Rotors



CDR1049K

DAF
Replacement Protex Fitting kit for
CDR1049 Disc Rotor

Connect Air Springs

NEW
RANGE!

BP1800P

Replaces...

BPW: 05.429.42.20.0 / 05.429.40.91.0 (TYPE30K)

Goodyear: 1R11-703

ContiTech: 940MB

ITAL: IT9070G

Phoenix: 1DK21K

Taurus: UR732-01



BP1801P

Replaces...

BPW: 05.429.42.25.0 / 05.429.40.03.0 (TYPE 30)

Goodyear: 1R11-700

ContiTech: 941MB

ITAL: IT9060G

Phoenix: 1DK21

Taurus: UR730-1



BP1802P

Replaces...

BPW: 05.429.42.26.0 / 05.429.40.01.0 (TYPE 36)

Goodyear: 1R14-708

ContiTech: 881MB

ITAL: IT9061G

Phoenix: 1DK32

Taurus: UR836-01



Protex Lined Brake Shoe Set

BP7097R



Replaces: BPW
Brake 95 - 360x200mm

Protex Camshafts



Stepped Shaft (43mm) x 1 1/2" x 10 Spline x 605mm Long

Replacement for: 350 x 200 ROR BMX AXLES

BP2126 21219321 RIGHT HAND

BP2127 21219322 LEFT HAND

Sealco Tractor Protection Valve



7700

Knorr-Bremse Relay Valve



JA304

MITSUBISHI FUSO
FS427 / FS417 / FS527 / FV517 / FV547

ATAP (Vic)

2-10 Bliss Court
Derrimut Victoria 3030
Ph: (03) 8369 1300
Fax: (03) 9689 1475

ATAP (NSW)

6/71 Rookwood Road
Yagoona NSW 2199
Ph: (02) 9791 8000
Fax: (02) 9793 9511

ATAP (Qld)

1 Success Street
Archerfield Qld 4108
Ph: (07) 3276 5200
Fax: (07) 3272 7983

ATAP (SA)

29a Hindmarsh Ave
Welland SA 5007
Ph: (08) 8346 7066
Fax: (08) 8346 8282

ATAP (WA)

2 Hazlehurst Street
Kewdale WA 6105
Ph: (08) 9352 9800
Fax: (08) 9353 3787